



Stock # 100513

\$139,000

\$188,000

Year 2007
Type Power
Brand Silverton
Category Motoryachts
Model 39 MY
Length (LOA) 43' 0"

Length (LOA) 43' 0" **Hours** 1,000

LocationBiloxi, MississippiStorage StatusNot currently in storage

Priced 30K below Market! We have a very Motivated seller here! All offer considered!

2007 Silverton 39 Motor Yacht with twin Cummins diesels making a total of 760 horse power, Kohler 8.5 KW 3 cylinder diesel generator.

This is a beautiful vessel!

You can enter this vessel from either side of the swim platform, whichever is best for the slip you have. I entered from the port side and walked into an outer aft salon area that is completely enclosed with a full camper canvas. This area has its own sink, ice maker, cabinet and couch for seating. You can go up to the bridge from there or into the main cabin.

Up on the bridge you will find room to seat 6 very comfortably to give the Captain som...

Read the entire description on the website by scanning the QR code below.







Stock # 100513

Details and Specifications

Engine & Mo	echanical				
# of Engines	2	Engine Year	2007	Engine Brand	Cummins
Engine Model	QSB 5.9	Engine Hours	1,000	Engine Size	380 hp
Fuel Type	Diesel	Fuel Capacity	334 gals	Configuration	Inboard

Dimensions	& Specificat	tions		
Length (LOA)	43'	Beam	14'	Minimum Draft 3' 11"
Dry Weight	24,000 lbs			

# of Cabins	2	# of Berths	3	Water Capacity	100 gals
Waste Capacity	60 gals	Has Generator	Yes Kohler 8.5 KW 3 cyl. diesel	Has Air Conditioning	Yes
Non-Smoking	Yes	Pet-Free	Yes		







Stock # 100513

Constructio	n reatures				
Designer	Silvert	Hull Material	Fiberglass	Hull Shape	Vee
Exterior Color	White	Interior Color	Wood/ Natural		







Stock # 100513

Features

_							
Α	 _	m	m	\sim	4 3	^r	•
\sim	 			u		OI.	13

• A/C + Heat

Cabin Lighting

Cabinets

Carpet

Countertops

Dinette

• Drink Holders

Freezer

Fridge

Galley

Handbasin

• Ice Maker

KVH Tracvision

Microwave

Mirror

Pressurized Water

System

Stove

Carpet

Tinted Windows

• Sofa: Sleeper

· Head: One In Each

Cabin

• Flooring: Hardwood &

• Shower: Each Cabin

• Sink: 4

• A/C: 3







Stock # 100513

Deck Gear

· Chairs & Seating

Courtesy Lights

· Dinghy

· Dock Lines

• Dropdown Bolsters

Eisenglass

· Additional Cockpit

Anchor

Settee

• Beverage Holders

Boarding Ladder

• Bow Rail

· Camper Canvas

W/screens

Canvas

• Fender Hangers

Fender Holders

Fenders

• Freshwater Washdown

• Full Enclosure

Raw Water Washdown

• Swim Ladder

Swim Platform

Transom Seating

Windshield

• Transom Door: Port And • Enclosure: Full For The

· Windshield Wipers

Gates: Port And
 Starboard Going To

Starboard

Bridge

• Sun Pad: Bow

Swim Platform

• Captain's Chair: 3







Stock # 100513

Electrical Systems

Ship's Power (12v DC)

Shore Power

Shore Power Cord

Speakers

Stereo

Tachometer

Transducer

Gauges

110v AC Outlets

12 V DC Outlets

• 4 Switch Circuit Breaker • ABYC Color Coded

Wiring

Accessory Switches

Alternator

Batteries

· Battery Charger

Battery Converter

Battery Perko Switch

Cable Hook Up

· CD Player

Circuit Breaker

Circuit Breaker Panel

· Cockpit Lighting

Docking Lights

• Engine Room Lighting

Horn

Hour Meter

Inverter

LED Lighting

MP3 Jack

Night Lighting

• Generator: Kohler 8.5

Diesel

• Satellite System: In

Motoin, For Tv's

Shore Power Retractor:

Auto

• Flat Screen TV: 3 LCD

Mechanical Systems

Hand Rails

· Holding Tanks

Stuffing Boxes

Turbocharger

Water Tanks

Windlass

• Bilge Pump

• Bottom Paint

Bow Pulpit

Bow Thruster

• Engine Alarms

• Engine Room

Fuel Filters

• GPS: Garmin

• Fuel Tank: 334 Gallons





Stock # 100513

Navigational Equipment

• Fuel Gauge

Navigation Lights

Satellite Tv

· Compass: Ritchie

• VHF: Raymarine Ray215 • Radar: Raymarine C80

Autopilot: Raymarine

• GPS/ Fishfinder/ Plotter:

DSC

72 Mile

Garmin 741 SX

Safety Equipment

Fire Extinguisher

• Fire Suppression System • Searchlight

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.

