



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(941) 257-0111

2003 Crownline 180BR

Stock # 144490



\$16,000

| | |
|---------------------------|--------------------------|
| Year | 2003 |
| Type | Power |
| Brand | Crownline |
| Category | Bowriders |
| Model | 180BR |
| Length (LOA) | 18' 0" |
| Hours | 390 |
| Location | Fitchburg, Wisconsin |
| Closest Major City | Madison, WI |
| Storage Status | Not currently in storage |

LOADED WITH UPGRADES, PROFESSIONALLY MAINTAINED!!!! LOW HOURS AND READY TO PLAY!!!!

Extremely clean, FAMILY FRIENDLY and well cared for Crownline bowrider.

The condition of this boat is better than expected as all original vinyl is in excellent shape with no rips, tears or fading! Hull has no cracks or nicks and the gel coat is very clean (wiped down after each use and waxed often). Graphics on the hull are like new with no UV fading.

Comes with large storm cover, small bimini top, dock bumpers and ski rope.

This Crownline is great for skiing and pulling tubes. The six-cylinder 4.3L Mercruiser engine has been maintenance friendly and is very easy on gas consumption. Getting up to 45mph ...

Read the entire description on the website by scanning the QR code below.



Information generated on Sep 28, 2024 3:00 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/144490>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(941) 257-0111

2003 Crownline 180BR

Stock # 144490

Details and Specifications

Engine & Mechanical

| | | | | | |
|----------------------|------------------|-----------------------|-----------|---------------------------|---------------------------------|
| # of Engines | 1 | Engine Year | 2003 | Engine Brand | MerCruiser |
| Engine Model | 4.3 | Engine Hours | 390 | Engine Size | 190 hp |
| Fuel Type | Gasoline | Fuel Capacity | 40 gals | Propeller Material | SS |
| Max Speed | 50 mph | Cruising Speed | 32 mph | Fuel Consumption | 7.5 gals/hour at Cruising Speed |
| Drive Brand | MerCruiser | Drive Model | Alpha One | Drive Type | Stern Drive |
| Configuration | Inboard/Outboard | | | | |

Dimensions & Specifications

| | | | | | |
|----------------------|-------|-------------------|-----------|----------------------|-------|
| Length (LOA) | 18' | Beam | 7' 6" | Minimum Draft | 1' 6" |
| Maximum Draft | 2' 8" | Dry Weight | 2,600 lbs | | |



Information generated on Sep 28, 2024 3:00 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/144490>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(941) 257-0111

2003 Crownline 180BR

Stock # 144490

Trailer Details

| | | | | | |
|----------------------|------|-------------------------|-----------------|------------------------|----------|
| Included | Yes | Trailer Year | 2003 | Trailer Brand | Prestige |
| Trailer Model | XELL | Trailer Material | Steel (painted) | # Axles | 1 |
| Brake Type | none | Spare Tire | Yes | Breakaway Hitch | No |

Accommodations & Passengers

| | | | | | |
|---------------------------|-----|----------------------|-----|-----------------------------|----|
| Passenger Capacity | 10 | Has Generator | No | Has Air Conditioning | No |
| Non-Smoking | Yes | Pet-Free | Yes | | |

Construction Features

| | | | | | |
|-----------------------|-------------|-------------------|-----------|-----------------------|-------------|
| Hull Material | Fiberglass | Hull Shape | Excellent | Exterior Color | White & Red |
| Interior Color | White & Red | | | | |

Features



Information generated on Sep 28, 2024 3:00 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/144490>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(941) 257-0111

2003 Crownline 180BR

Stock # 144490

Accommodations

- Carpet

Construction Features

- Gel Coat

Deck Gear

- Cleats
- Walk Through Windshield
- Beverage Holders
- Lines: Ski Rope
- Bimini: Excellent
- Sun Pad: Bow & Stern
- Compartment Storage
- Windshield
- Boat Cover
- Ladder: Integrated Swim Platform
- Captain's Chair: Cockpit / Passenger
- Bench Seat: Aft
- Glove Box
- Aft Deck Sun Pad
- Bow Cover
- Swim Platform: Integrated Swim Ladder
- Passenger Seat: Captains Chair
- Swim Ladder
- Anchor Locker
- Steering Wheel: Tilt
- Ski Storage: Floor
- Fenders: Bumpers



Information generated on Sep 28, 2024 3:00 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/144490>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(941) 257-0111

2003 Crownline 180BR

Stock # 144490

Electrical Systems

- Lighting
- Oil Pressure Gauge
- Ship's Power (12v DC)
- Volt Meter
- Water Temp Gauge
- 12 V DC Outlets
- Accessory Switches
- Alternator
- Amplifier
- Bluetooth
- Engine Kill Switch
- Fuse Panel
- Horn
- Ignition: Electric
- Circuit Breaker: Bilge
- Speakers: 6 Sony Marine

Mechanical Systems

- Bilge Blower
- Bilge Pump
- Electronic Throttle/shift
- Engine Alarms
- Fuel Injected
- Power Tilt & Trim
- Throttle/shift: With Trim
- Fuel Tank Location: Stern Port
- Engine Location: Stern
- Number Of Eng Cylinders: 6

Navigational Equipment

- Depth Instrument In Dash
- Water Temp Instrument
- Sound System: 6 Sony Marine Speakers



Information generated on Sep 28, 2024 3:00 AM

Please view this listing online for up-to-date information:

<https://www.popsells.com/view/144490>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(941) 257-0111

2003 Crownline 180BR

Stock # 144490

Safety Equipment

- Fire Extinguisher
- Owners Manual



Information generated on Sep 28, 2024 3:00 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/144490>

Pop

Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233

Pop

Contact Pop
(941) 257-0111

2003 Crownline 180BR

Stock # 144490



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Sep 28, 2024 3:00 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/144490>