



**Pop Sells**  
5717 Bessie Drive  
Sarasota, Florida 34233

**Pop**  
**Contact Pop**  
(941) 257-0111

# 1986 Wellcraft 250 Sportsman

Stock # 145423



\$15,500

Year	1986
Type	Power
Brand	Wellcraft
Category	Walkarounds
Model	250 Sportsman
Length (LOA)	25' 6"
Hours	Unavailable
Location	Merrick, New York
Closest Major City	Hempstead, NY
Storage Status	Not currently in storage

**Great condition 250 Sportsman with a 350 HP 2006 Mercruiser 5.7L and a 2016 new Apha One drive. Turn Key Ready.**

Read the entire description on the website by scanning the QR code below.



Information generated on Sep 27, 2024 7:02 PM  
Please view this listing online for up-to-date information:  
<https://www.popsells.com/view/145423>



# 1986 Wellcraft 250 Sportsman

Stock # 145423

## Details and Specifications

### Engine & Mechanical

# of Engines	1	Engine Year	2006	Engine Brand	MerCruiser
Engine Model	5.7L	Engine Hours	Unavailable	Engine Size	350 hp
Fuel Type	Gasoline	Fuel Capacity	100 gals	Drive Brand	MerCruiser
Drive Model	Alpha One	Drive Type	Stern Drive	Configuration	Inboard/Outboard

### Dimensions & Specifications

Length (LOA)	25' 6"	Beam	8'
--------------	--------	------	----

### Trailer Details

Included	No
----------	----





# 1986 Wellcraft 250 Sportsman

Stock # 145423

## Accommodations & Passengers

<b>Passenger Capacity</b>	8	<b># of Cabins</b>	1	<b>Sleeping Capacity</b>	2
<b># of Berths</b>	2	<b>Has Generator</b>	No	<b>Has Air Conditioning</b>	No
<b>Non-Smoking</b>	Yes	<b>Pet-Free</b>	Yes		

## Construction Features

<b>Hull Material</b>	Fiberglass	<b>Hull Shape</b>	Modified Deep-v
----------------------	------------	-------------------	-----------------



**Pop**

**Pop Sells**

5717 Bessie Drive  
Sarasota, Florida 34233

**Pop**

**Contact Pop**  
(941) 257-0111

# 1986 Wellcraft 250 Sportsman

Stock # 145423



**Scan the QR code or click the link in the footer to view more photos.**

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Sep 27, 2024 7:02 PM  
Please view this listing online for up-to-date information:  
<https://www.popsells.com/view/145423>