



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(941) 257-0111

1980 Marine Trader 34 DC

Stock # 198813



\$38,900

~~\$50,000~~

Year	1980
Type	Power
Brand	Marine Trader
Category	Trawlers
Model	34 DC
Length (LOA)	33' 6"
Hours	2,700
Location	Inglis, Florida
Closest Major City	Ocala, FL
Storage Status	Not currently in storage

The Double Cabin trawler that everyone wants! This baby lives in Fresh water and is decked out and ready to set sail into sunset waters you dream of!

This 1980 MARINE TRADER 34 double cabin is in very good condition for its age and use. It appears from the pictures and information found about boat that there is a full length keel that drops more than 2 ft near stern and provides protection for the rudder and propeller. The trawler has two staterooms and two heads. Woodwork reconditioning is about half done. Boat has outside window covers. Boat featured in online blog <https://trawler-beach-house.blogspot.com/2009/03/marine-trader-review.html>

Read the entire description on the website by scanning the QR code below.



Information generated on Sep 30, 2024 5:27 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/198813>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(941) 257-0111

1980 Marine Trader 34 DC

Stock # 198813

Details and Specifications

Engine & Mechanical

# of Engines	1	Engine Year	1980	Engine Brand	Lehman
Engine Model	2715E	Engine Hours	2,700	Engine Size	110 hp
Fuel Type	Diesel	Fuel Capacity	300 gals	Configuration	Inboard

Dimensions & Specifications

Length (LOA)	33' 6"	Length at Water	30' 3"	Beam	11' 9"
Maximum Draft	3' 6"	Dry Weight	17,000 lbs		

Trailer Details

Included	No
-----------------	----



Information generated on Sep 30, 2024 5:27 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/198813>



Pop Sells
 5717 Bessie Drive
 Sarasota, Florida 34233

Pop **Contact Pop**
 (941) 257-0111

1980 Marine Trader 34 DC

Stock # 198813

Accommodations & Passengers

# of Cabins	2	Sleeping Capacity	4	# of Berths	3
Can Live Aboard	Yes	Water Capacity	150 gals	Waste Capacity	40 gals
Has Generator	Yes Kubota	Has Air Conditioning	Yes 13500	Non-Smoking	Yes
Pet-Free	Yes				

Construction Features

Hull Material	Fiberglass	Hull Shape	Semi Displacement
----------------------	------------	-------------------	-------------------



Information generated on Sep 30, 2024 5:27 PM
 Please view this listing online for up-to-date information:
<https://www.popsells.com/view/198813>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(941) 257-0111

1980 Marine Trader 34 DC

Stock # 198813

Features

Accommodations

- Aft Stateroom
- Cabin Lighting
- Cabinets
- Countertops
- Dinette
- Nav Station
- Refrigerator
- Shower
- Sink - Cabin
- Stove / Oven
- TV
- V Berth
- Head: 2

Construction Features

- Bottom Paint Antifouling

Deck Gear

- Anchor
- Anchor Rode
- Electric Winch
- Hand Rails
- Windlass

Electrical Systems

- Battery Switch
- Circuit Breaker Panel
- Fuel Gauge
- Horn
- Hour Meter
- Number Of Batteries: 6



Information generated on Sep 30, 2024 5:27 PM

Please view this listing online for up-to-date information:

<https://www.popsells.com/view/198813>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(941) 257-0111

1980 Marine Trader 34 DC

Stock # 198813

Mechanical Systems

- Engine Alarms
- Heat Exchanger
- Holding Tank Alarm System
- Holding Tanks
- Oil Changing System
- Radar Arch/mast

Navigational Equipment

- Autopilot
- Chartplotter
- Compass
- GPS / Plotter
- Radar
- Running Lights
- Satellite Phone
- VHF
- VHF Antenna



Information generated on Sep 30, 2024 5:27 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/198813>



Pop Sells
 5717 Bessie Drive
 Sarasota, Florida 34233

Pop **Contact Pop**
 — (941) 257-0111

1980 Marine Trader 34 DC

Stock # 198813



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Sep 30, 2024 5:27 PM
 Please view this listing online for up-to-date information:
<https://www.popsells.com/view/198813>