



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Steven Wise
(414) 550-0083
steve@popsells.com

1993 Catalina 18 Capri

Stock # 244893



\$10,250

Year	1993
Type	Sail
Brand	Catalina
Category	Daysailer
Model	18 Capri
Length (LOA)	18' 0"
Location	Pequot Lakes, Minnesota
Closest Major City	St. Cloud, MN
Storage Status	Not currently in storage

18' Capri ! A great family daysailer that is easy to trailer, launch and sail!

Beautiful 18' Catalina Capri daysailer that has overnight capabilities! Can sleep up to 4 persons. Includes a Harken Roller furling Jib and a 135% Genoa! Four (4) winches help make this a single-handed operation from the cockpit so enjoy a great day on the lake without having to worry about moving fore and aft on the boat! Includes a knot/depth meter as well as a compass to help with navigation. Accessories include fenders for docking, an anchor, and a swim ladder. The cockpit cushions are included as well. More pics coming soon!

Read the entire description on the website by scanning the QR code below.



Information generated on Feb 25, 2024 9:56 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/244893>



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact Steven Wise
(414) 550-0083
steve@popsells.com

1993 Catalina 18 Capri

Stock # 244893

Details and Specifications

Engine & Mechanical

# of Engines	1	Engine Brand	Nissan	Engine Size	5 hp
Fuel Type	Gasoline	Configuration	Outboard - 4 Stroke		

Dimensions & Specifications

Length (LOA)	18'	Beam	7' 7"	Minimum Draft	2' 4"
Cockpit Location	Aft	Dry Weight	1,500 lbs		

Trailer Details

Included	Yes	Trailer Year	1993	Trailer Brand	Spartan
Trailer Material	steel	# Axles	1	Breakaway Hitch	No



Information generated on Feb 25, 2024 9:56 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/244893>



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact Steven Wise
(414) 550-0083
steve@popsells.com

1993 Catalina 18 Capri

Stock # 244893

Accommodations & Passengers

Passenger Capacity	4	# of Cabins	1	Sleeping Capacity	4
# of Berths	2	Has Generator	No	Has Air Conditioning	No
Non-Smoking	Yes	Pet-Free	Yes		

Construction Features

Hull Material	Fiberglass	Hull Shape	Wing Keel	Exterior Color	Wht
----------------------	------------	-------------------	-----------	-----------------------	-----

Features

Accommodations

- Cabin Lighting
- Porta-potty
- V Berth

Construction Features

- Bottom Paint Antifouling



Information generated on Feb 25, 2024 9:56 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/244893>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Steven Wise
(414) 550-0083
steve@popsells.com

1993 Catalina 18 Capri

Stock # 244893

Deck Gear

- Anchor
- Swim Ladder
- Cockpit Cushions

Electrical Systems

- Deck Lights
- Stereo
- Battery Tender: Solar
- Number Of Batteries: 1

Mechanical Systems

- Rudder

Navigational Equipment

- Tiller Plus Extension
- Compass
- Navigation Lights
- Depth/ Speed Instrument

Rigging

- Boom
- Boom Vang
- Topping Lift
- Mast
- Running Rigging
- Sloop Rig
- Standing Rigging
- Winches - Manual: (4)



Information generated on Feb 25, 2024 9:56 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/244893>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Steven Wise
(414) 550-0083
steve@popsells.com

1993 Catalina 18 Capri

Stock # 244893

Sails

- Main Sail
- Roller Furling Jib: 135
Genoa



Information generated on Feb 25, 2024 9:56 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/244893>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Steven Wise
(414) 550-0083
steve@popsells.com

1993 Catalina 18 Capri

Stock # 244893



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Feb 25, 2024 9:56 AM

Please view this listing online for up-to-date information:

<https://www.popsells.com/view/244893>