



Lempster, New Hampshire

## 1967 Boston Whaler Nauset 17

Stock # 250242



\$17,800

Location

Year 1967 Type Power

**Brand** Boston Whaler

Category Skiffs

Model Nauset 17

Length (LOA) 17' 0"

Hours Unavailable

Closest Major City Concord, NH

Storage Status On the hard

### Super nice skiff in good condition, bimini top and well maintained!

This 1967 BOSTON WHALER NAUSET 17 is a one-of-a-kind!

The boat hails from MA where the current purchased her in 2016 and transported her to NH where she was used through 2019 on a freshwater lake only.

THE BOAT DOES NOT HAVE AN ENGINE. The current owner removed the engine as he purchased a new 2018 Yamaha 90 hp 4-stroke for the boat, (which the boat had no problem handling), and had it mounted on his current boat to use.

The seller reports that in 2018 the exterior boat hull was refurbished by a professional refurbishing/fiberglass shop in NH.

In addition, in 2019, he refurbished the interior...

Read the entire description on the website by scanning the QR code below.







Stock # 250242

# **Details and Specifications**

Engine Hours	Unavailable	Fuel Type	Gasoline	Fuel Capacity	12 gals
	0				
Dimensions	& Specificat	ions			
Length (LOA)	17'	Beam	6' 2"	Dry Weight	500 lbs
Trailer Deta	ils				
Included	Yes	Trailer Brand	Miscellaneous	Breakaway Hitch	No
Accommoda	ntions & Pass	engers			
Has Generator	No	Has Air Conditioning	No	Non-Smoking	Yes
	Yes				





Stock # 250242

#### **Construction Features**

**Hull Material Fiberglass** 

#### **Features**

#### **Construction Features**

· Bottom Paint

Antifouling: Spring 2019

#### **Deck Gear**

- Bench Seat
- Transom Closed
- Captain's Chair
- · Cleats Fixed

- Cockpit Seating
- Snap-on Cushions
- Steering Wheel: Original Bimini: New 2019

Wheel/mahogany

### **Electrical Systems**

- Fuel Gauge
- Hour Meter
- Tachometer
- · Volt Meter

• Number Of Batteries: 1







Stock # 250242

### **Mechanical Systems**

• Bilge Pump

• Number Of Fuel Tanks: 2

(6 Gallon Tanks)







Stock # 250242





Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.

