



1986 Chris-Craft Catalina 426

Stock # 260595



\$95,000

Year1986TypePowerBrandChris-CraftCategoryMotoryachtsModelCatalina 426

Length (LOA) 42' 0" **Hours** 2,998

Location Lynn, Massachusetts

Closest Major City Boston, MA

Storage Status Currently winterized

Great condition yacht ready for the Great Loop or nice live aboard.

This classic Chris Craft Catalina 426, located just north of Boston, is in excellent condition.

"I am a little OCD," says the seller. "I wouldn't hesitate to take her to Florida tomorrow on her own bottom."

All annual maintenance is done in the fall including new zincs and bottom paint before being winterized. Complete maintenance records are onboard, all the way back to the original purchase invoice. Yup, a little OCD.

Manufacturer manuals are also included for every system on the boat from radar array to bilge pumps and everything in between.

Boarding the boat from the large swim platform bring...

Read the entire description on the website by scanning the QR code below.







1986 Chris-Craft Catalina 426

Stock # 260595

Details and Specifications

# of Engines	2	Engine Year	1986	Engine Brand	Caterpillar
Engine Model	3208 TA	Engine Hours	2,998	Engine Size	375 hp
Fuel Type	Diesel	Fuel Capacity	480 gals	Propeller Material	Nibral
Max Speed	20 mph	Cruising Speed	14 mph	Drive Type	Direct Drive
Configuration	Inboard				

	40.	_		
Length (LOA)	42'	Beam	14' 9"	Maximum Draft 3' 9"
Dry Weight	37,000 lbs	Bridge Clearance	18'	







1986 Chris-Craft Catalina 426

Stock # 260595

Passenger Capacity	12	# of Cabins 4	Sleeping Capacity	8
# of Berths	4	Can Live AboardYes	Water Capacity	200 gals
Waste Capacit	y 45 gals	Has Generator Yes	Has Air Conditioning	Yes 16000 BTU Marine

Constructio	n Features				
Hull Material	Fiberglass	Hull Shape	Deep Vee	Exterior Color	White
Interior Color	Blue/mahogany				







1986 Chris-Craft Catalina 426

Stock # 260595

Features

_												
Л	•	^	^	m	m	\mathbf{a}	М	2	•	^	n	c
_	•	·	u			u	ч	а		u		3

Cabin Lighting

Cabinets

Carpet - Cabin

· Central Vacuum System

Dinette

Freezer

• Fridge/freezer- Full Size • Hanging Locker

Head

Heat

Ice Box

Microwave

Mirror

Port Holes

Pressurized Water

• Refrigerator

System

Salon

Settee

Shower

• Sink - Galley

Stateroom - Aft

Stateroom - Forward

Stove / Oven


• Window Treatments

Construction Features

• Bottom Paint Antifouling • Stringers







1986 Chris-Craft Catalina 426

Stock # 260595

Deck Gear

AnchorAı

Bolster Seat

Compartment Storage

Glove Box

Passenger Seat

Swim Ladder

Windlass

Anchor Locker

Bow Rail

• Dinghy Lift

Hard Top

Removable Seats

Swim Platform

• Windshield - One Piece

Anchor Rode

· Cleats - Fixed

Fender Locker

Hatch Covers

• Sea Cocks

• Toe Rail

· Beverage Holders

· Cockpit Seating

· Freshwater Washdown

Helm Light

· Steering Wheel

· Transom - Closed

Electrical Systems

110v AC Outlets

Bluetooth

Fuel Gauge

• Shower Sump Pump

USB Port

Shore Power

12 V DC Outlets

Circuit Breaker Panel

Fuse Panel

r use runer

Speedometer

Volt Meter

• Shore Power Cord: 3

AC Electric Panel

· Windshield Wipers

• Cockpit Accent Lighting

• Number Of Batteries: 3

• Horn

Stereo

Water Heater

• Hour Meter

Tachometer

· Battery Switch

Courtesy Lights

• Oil Pressure Gauge





1986 Chris-Craft Catalina 426

Stock # 260595

Mechanical Systems

Bilge Blower

Closed Water Cooling

Engine Alarms

· Fuel Injected

Holding Tanks

Macerator

Sys.

Rudder

· Throttle/shift: Mech

Water Tanks

• Bilge Pump: 4

• Number Of Fuel Tanks: 3 • Date Impellers

Replaced: 2019

Navigational Equipment

Compass

Covers - Display

• GPS / Plotter

• GPS Antenna

Masthead Light:

VHF Antenna

Navigation Lights

Radar Array

VHF

Safety Equipment

Air Horn

Carbon Monoxide

Engine Kill Switch

• EPIRB

Gas/fume Detector

Grab Rails

Detector

Halon Fire Suppression

· Life Sling

Owner's Manual

Spotlight

· Sump Pump







1986 Chris-Craft Catalina 426

Stock # 260595



















Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.

