



2007 Donzi 27 ZR

Stock # 304626



\$53,000

\$55,600

Year 2007 Type Power Brand Donzi

Category High Performance

 Model
 27 ZR

 Length (LOA)
 27' 2"

 Hours
 300

Location Kelowna, British Columbia **Storage Status** Not currently in storage

GREAT CONDITION & READY FOR THE WATER!!! POWERED BY A 425HP MERCURY!!!

Fast and fun, this Donzi is ready to hit the water and turn some heads in the process! 496 cubic inches of pure V8 power will get you where you want to go in a hurry and, according to the seller, there's just over 300 hours on it. The well-cared-for hull and upholstery will have you looking good while you're running. When you see it, it will be obvious just how well the seller has cared for this vessel. Don't let this one slip through your fingers! Call to set up a showing before it disappears. *** 48 hours minimum notice for showings, please. ***

Read the entire description on the website by scanning the QR code below.







2007 Donzi 27 ZR

Stock # 304626

Details and Specifications

# of Engines	1	Engine Year	2007	Engine Brand	Mercruiser
Engine Model	496 Mag HO	Engine Hours	300	Engine Size	425 hp
Fuel Type	Gasoline	Fuel Capacity	90 gals	Propeller Material	Stainless Steel
Drive Brand	Mercruiser	Drive Model	Bravo One	Drive Type	Stern Drive
Configuration	Inboard/Outboard				

Length (LOA)	27' 2"	Beam	8' 4"	Maximum Draft 2' 8"
Dry Weight	5,500 lbs			

Trailer Deta	ails		
ncluded	No		







2007 Donzi 27 ZR

Stock # 304626

Has Generator	- No	Has Air Conditioning	No	
Constructio	n Features			

Features

Accommodations

Porta-potty

Deck Gear

- Swim Ladder
- Cockpit Seating
- Cleats Pull Up
- · Captain's Chair







2007 Donzi 27 ZR

Stock # 304626

Electrical Systems

- Water Temp Gauge
- Volt Meter
- Tachometer
- Speedometer

- Power Trim & Tilt Gauge
 Oil Pressure Gauge
- Hour Meter
- Fuel Gauge

Mechanical Systems

- Throttle/shift: Mech
- Power Trim & Tilt
- Bilge Pump
- · Bilge Blower

Navigational Equipment

Compass

Safety Equipment

Horn







2007 Donzi 27 ZR

Stock # 304626



















Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.

