

Pop Sells 5717 Bessie Drive Sarasota, Florida 34233

Pop Contact Pop (941) 257-0111

1987 Sea Ray 270 Sundancer

Stock # 306314



\$12,000

Year	1987
Туре	Power
Brand	Sea Ray
Category	Express Cruisers
Model	270 Sundancer
Length (LOA)	29' 3"
Hours	Unavailable
Location	Bayshore, New York
Closest Major City	Islip, NY
Storage Status	Currently in storage

1987 Sea Ray with twin Mercruiser engines ready to take on the waters with its new owners!

Come aboard this 1987 Sea Ray 270 Sundancer located on Long Island in New York! The classic Sea Ray hasn't been around this many years by chance, come see the quality in this vessel! The swim platform allows for easy space to get on and off the boat. Seating along the transom allows for a few friends to come aboard and have a good time! The Captain's seat and cockpit are comfortable for all to drive the boat throughout the day. The cabin contains a head, a vberth and a galley with a dinette. Come check it out!

Read the entire description on the website by scanning the QR code below.





1987 Sea Ray 270 Sundancer

Stock # 306314

Details and Specifications

# of Engines	2	Engine Year	1987	Engine Brand	Mercruiser
Engine Hours	Unavailable	Fuel Type	Gasoline	Fuel Capacity	120 gals
Drive Brand	Mercruiser	Drive Type	Stern Drive	Configuration	Inboard/Outboard
	& Specificat		10'	Minimum Draft	1' 10"
Dimensions Length (LOA) Maximum Draf	29' 3"	Beam Dry Weight	10' 6,700 lbs	Minimum Draft	: 1' 10"
Length (LOA)	29' 3"	Beam		Minimum Draft	: 1' 10"





1987 Sea Ray 270 Sundancer

Stock # 306314

Can Live Aboa	ard Yes	Water Capacity 28 gals	Has Generator	No
Has Air Conditioning	Yes	Non-Smoking Yes	Pet-Free	Yes

Constructio	n Features
Hull Material	Fiberglass

Features





Information generated on Sep 29, 2024 8:57 AM Please view this listing online for up-to-date information: https://www.popsells.com/view/306314



1987 Sea Ray 270 Sundancer

Stock # 306314



Compass





Pop Sells 5717 Bessie Drive Sarasota, Florida 34233

1987 Sea Ray 270 Sundancer

Stock # 306314



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Sep 29, 2024 8:57 AM Please view this listing online for up-to-date information: https://www.popsells.com/view/306314