



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact James Schwartz
(405) 550-3815
james@popsells.com

1989 Sea Ray 268 Sundancer

Stock # 323464



\$8,950

~~\$12,750~~

Year	1989
Type	Power
Brand	Sea Ray
Category	Express Cruisers
Model	268 Sundancer
Length (LOA)	28' 3"
Hours	780
Location	Perry, Kansas
Closest Major City	Topeka, KS
Storage Status	Not currently in storage

Sundancer 268 just right for cruising the lake and fun weekend trips!

The 268 Sundancer is one of Sea Ray's most popular models. This is large enough to spend the weekend with family and friends and have plenty of room.

The helm seat is set up to make you the captain of fun so you can begin enjoying this fine boat.

For your entertainment, there is an AM/FM stereo. And the layout gives you multiple areas to entertain.

The boat has a hot and cold water pressure system. You will have hot water in the galley and the head. The galley has a sink and a two-burner alcohol cooktop. The galley also has a 120v/12v fridge.

The cabin has a V-berth forward with a privacy curtain...

Read the entire description on the website by scanning the QR code below.



Information generated on Sep 30, 2024 2:46 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/323464>



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact James Schwartz
(405) 550-3815
james@popsells.com

1989 Sea Ray 268 Sundancer

Stock # 323464

Details and Specifications

Engine & Mechanical

# of Engines	1	Engine Year	1989	Engine Brand	MerCruiser
Engine Model	7.4L	Engine Hours	780	Engine Size	330 hp
Fuel Type	Gasoline	Fuel Capacity	100 gals	Max Speed	45 mph
Drive Brand	MerCruiser	Drive Model	Alpha One	Drive Type	Stern Drive
Configuration	Inboard/Outboard				

Dimensions & Specifications

Length (LOA)	28' 3"	Beam	8' 6"	Minimum Draft	1' 4"
Maximum Draft	2' 10"	Dry Weight	5,475 lbs		



Information generated on Sep 30, 2024 2:46 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/323464>



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact James Schwartz
(405) 550-3815
james@popsells.com

1989 Sea Ray 268 Sundancer

Stock # 323464

Trailer Details

Included	Yes	Trailer Year	1994	Trailer Brand	Heritage
Trailer Model	XT	Trailer Material	Steel	# Axles	2
# Brakes	1	Brake Type	Surge	Breakaway Hitch	No

Accommodations & Passengers

Water Capacity	24 gals	Has Generator	No	Has Air Conditioning	No
Non-Smoking	Yes	Pet-Free	Yes		

Construction Features

Hull Material	Fiberglass	Hull Shape	Modified-vee	Exterior Color	White/green
Interior Color	White/green				

Features



Information generated on Sep 30, 2024 2:46 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/323464>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact James Schwartz
(405) 550-3815
james@popsells.com

1989 Sea Ray 268 Sundancer

Stock # 323464

Accommodations

- Pressurized Water System
- Refrigerator
- Shower
- Sink - Galley
- Stove
- V Berth

Deck Gear

- Bench Seat
- Captain's Chair
- Cleats - Pop-up
- Full Enclosure
- Swim Ladder
- Swim Platform

Electrical Systems

- 12 V DC Outlets
- Battery Switch
- Courtesy Lights
- Power Trim & Tilt Gauge
- Speedometer
- Stereo
- Tachometer

Mechanical Systems

- Bilge Pump
- Trim Tabs



Information generated on Sep 30, 2024 2:46 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/323464>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact James Schwartz
(405) 550-3815
james@popsells.com

1989 Sea Ray 268 Sundancer

Stock # 323464

Navigational Equipment

- Compass
- Navigation Lights
- VHF
- VHF Antenna

Safety Equipment

- Engine Kill Switch



Information generated on Sep 30, 2024 2:46 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/323464>



Pop Sells


5717 Bessie Drive
Sarasota, Florida 34233



Contact James Schwartz
(405) 550-3815
james@popsells.com

1989 Sea Ray 268 Sundancer

Stock # 323464



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Sep 30, 2024 2:46 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/323464>