



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact Dennis Sherrer
(206) 271-4410
denniss@popsells.com

2003 Forest River M-B Cruiser

Stock # 335540



\$33,500

Year	2003
Type	Motor
Brand	Forest River
Manufactured By	Forest River
Category	Class B
Model	M-B Cruiser
Length	22' 0"
Miles	53,000
Location	Kent, Washington
Storage Status	Not currently in storage

2003 Forest River M-B Cruiser 220 - Class B Motorhome in Kent, WA

Read the entire description on the website by scanning the QR code below.



Information generated on Jan 16, 2024 5:39 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/335540>



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact Dennis Sherrer
(206) 271-4410
denniss@popsells.com

2003 Forest River M-B Cruiser

Stock # 335540

Details and Specifications

Engine & Mechanical

Engine Brand	Chrysler	Engine Model	V8	Miles	53,000
Fuel Type	Diesel				

Dimensions & Specifications

Length	22'
--------	-----

Accommodations & Passengers

Sleep Capacity	3	Bunk Beds	No	# of Slides	0
----------------	---	-----------	----	-------------	---

Construction Features

Tag Axle	No
----------	----



Information generated on Jan 16, 2024 5:39 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/335540>



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact Dennis Sherrer
(206) 271-4410
denniss@popsells.com

2003 Forest River M-B Cruiser

Stock # 335540

Living Areas

# of Full Bathrooms	1	Non-Smoking	Yes
---------------------	---	-------------	-----



Information generated on Jan 16, 2024 5:39 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/335540>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Dennis Sherrer
(206) 271-4410
denniss@popsells.com

2003 Forest River M-B Cruiser

Stock # 335540



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Jan 16, 2024 5:39 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/335540>