



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233

Pop
Contact Pop
(888) 761-7011

2019 Vengeance 40d12

Stock # 382295



\$61,800

Year	2019
Type	Trailer
Brand	Vengeance
Manufactured By	Forest River
Category	Fifth Wheel
Model	40d12
Length	42' 10"
Miles	Unavailable
Location	Knightdale, North Carolina
Closest Major City	Raleigh, NC
Storage Status	Not currently in storage

2019 Vengeance Toy Hauler by Forest River. 12 ft patio/porch with TV and fireplace!

Read the entire description on the website by scanning the QR code below.



Information generated on Sep 17, 2024 2:20 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/382295>



2019 Vengeance 40d12

Stock # 382295

Details and Specifications

Engine & Mechanical

# of Axles	3	Age of tires	72 mos.
------------	---	--------------	---------

Dimensions & Specifications

Length	42' 10"	Width	8' 6"	Height	13' 4"
Weight	14,153 lbs	Weight Rating (GVWR)	19,500		

Accommodations & Passengers

Sleep Capacity	8	# of Sleeping Areas	4	Bunk Beds	No
Water Capacity	100 gals	Gray Water Capacity	100 gals	Waste Capacity	100 gals
Has Generator	Yes Onan QG 5500	# of Slides	2	Has Air Conditioning	Yes 42000





2019 Vengeance 40d12

Stock # 382295

Construction Features

Body Material	Fiberglass	Exterior Color	White/gray/blue	Hitch Type	Fifth Wheel
Rear Loading	Ramp	Floor Type	Vinyl	Jack Stands	Hydraulic

Living Areas

# of Full Bathrooms	1	# of Half Bathrooms	1	Non-Smoking	Yes
Has King Bed	Yes				

Outdoor Areas

# of Awnings	1	# of Side Doors	2
---------------------	---	------------------------	---

Dining

Propane Capacity	60 lbs
-------------------------	--------



Pop

Pop Sells



5717 Bessie Drive
Sarasota, Florida 34233

Pop

Contact Pop
(888) 761-7011

2019 Vengeance 40d12

Stock # 382295



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Sep 17, 2024 2:20 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/382295>