

Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(888) 761-7011

2020 Cougar 302RLS

Stock # 397180



\$35,000

~~\$38,900~~

Year	2020
Type	Trailer
Brand	Cougar
Manufactured By	Keystone
Category	Fifth Wheel
Model	302RLS
Length	34' 7"
Miles	0
Location	Bonne Terre, Missouri
Closest Major City	St. Louis, MO
Storage Status	Currently in storage

EXTREMELY SPACIOUS WITH 3 SLIDES!!! GREAT CONDITION & READY FOR THE ROAD!!

The Cougar 302RLS is renowned for its expansive rear living area, the focal point for relaxation and entertainment. This space offers a comfortable retreat after a day of exploration, featuring large panoramic windows, plush seating, and high-quality furnishings.

The rear sofa and theater seating provide ample seating for guests, while the cozy fireplace creates a warm ambiance on cooler evenings. With thoughtful touches such as hidden storage compartments and USB charging ports integrated into the furniture, the rear living area is designed for comfort and functionality, ensuring that travelers feel right at home wherever they...

Read the entire description on the website by scanning the QR code below.



Information generated on Oct 4, 2024 7:33 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/397180>



2020 Cougar 302RLS

Stock # 397180

Details and Specifications

Engine & Mechanical

Miles	0	Fuel Type	None	# of Axles	2
Age of tires	54 mos.				

Dimensions & Specifications

Length	34' 7"	Width	8'	Height	13' 5"
Weight	10,110 lbs	Weight Rating (GVWR)	12,160		

Accommodations & Passengers

Sleep Capacity	6	# of Sleeping Areas	2	Bunk Beds	No
Water Capacity	81 gals	Gray Water Capacity	76 gals	Waste Capacity	38 gals
Has Generator	No	# of Slides	3	Has Air Conditioning	Yes 15,000 BTU





2020 Cougar 302RLS

Stock # 397180

Construction Features

Exterior Color	Tan And White	Interior Color	Grey And Brown	Hitch Type	Fifth Wheel
Floor Type	Vinyl	Jack Stands	Electric		

Living Areas

# of Full Bathrooms	1	Non-Smoking	Yes	Pet-Free	Yes
Has Washer/Dryer Hookup	Yes				

Outdoor Areas


# of Awnings	2	# of Side Doors	1
--------------	---	-----------------	---

Dining

Propane Capacity	60 lbs
------------------	--------

Features





Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(888) 761-7011

2020 Cougar 302RLS

Stock # 397180

Dining Features

- Cabinets
- Dinette
- Double Kitchen Sink
- Kitchen Island
- Microwave
- Oven
- Refrigerator - Mini
- Refrigerator/freezer
- Stove

Entertainment Features

- Digital TV Antenna
- Interior Lighting
- TV

Living Features

- Storage
- Air Conditioning
- Bathroom Sink
- Bed - Full/queen
- Black Water Flush System
- Carpet
- Ceiling Vents
- Central Heat
- Clothes Washer Dryer Prep
- Control Center
- Dinette Sleeper
- Medicine Cabinet
- Recliner - Stadium Style
- Shower
- Sink
- Skylight
- Slide-out
- Sofa Sleeper
- Toilet
- Vanity
- Water Heater



Information generated on Oct 4, 2024 7:33 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/397180>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(888) 761-7011

2020 Cougar 302RLS

Stock # 397180

Mechanical Systems

- 110 Lighting
- 110 Outlets
- Batteries - House
- City Water Hook Up
- Power Cord
- AC Electrical Power
- Backup Monitor
- Power Jacks: Front
- Hitch: 5th Wheel
- Tire Date Code: 2919

Outside Features


- Exterior Kitchen
- Exterior Shower
- Exterior Speakers
- Awning - Entry
- Awning - Slide-out
- Entry Assist Grab Handle
- Entry Steps - Pull Out
- Exterior Grill
- Exterior Storage
- Leveling Jacks
- Propane Tanks
- Roof Access Ladder

Safety Equipment

- Brakes
- Emergency Exit
- Back Up Camera



Information generated on Oct 4, 2024 7:33 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/397180>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(888) 761-7011

2020 Cougar 302RLS

Stock # 397180



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Oct 4, 2024 7:33 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/397180>