

Pop Sells 5717 Bessie Drive Sarasota, Florida 34233

1983 Universal Trawler Litton Europa 41

Stock # 402182



\$72,200

Year	1983
Туре	Powerboat
Brand	Universal Trawler
Category	Trawlers
Model	Litton Europa 41
Length (LOA)	41' 0"
Hours	3,100
Location	Pasadena, Maryland
Closest Major City	Glen Burnie, MD
Storage Status	In the water

Contact Robert Hill

(410) 371-5657 roberth@popsells.com

41' trawler, the popular Europa model with entry aft into a large, comfortable salon with superb viability!

Looking to check off a bucket list item by doing the Great Loop on the perfect live aboard? This 1983 Universal Trawler was designed to take you out on the water for an extended period in comfort and safety! From the elevated flybridge, you can command the waters you are navigating with ease and enjoy the breathtaking views from high above. The yacht is in very good shape and the engines have been well maintained by the current owner. All systems on board are in good working order and the yacht has recently redone bottom paint.

Read the entire description on the website by scanning the QR code below.







Stock # 402182

Details and Specifications

Engine Hours	3,100	Engine Size	120 hp
Fuel Capacity	600 gals	Configuration	Inboard
	ons		







Stock # 402182

Passenger Capacity	14	# of Cabins	2	Sleeping Capacity	4
Can Live Aboar	d Yes	Water Capacity	/ 80 gals	Waste Capacity	40 gals
Has Generator	Yes Westerly 7.7	Has Air Conditioning	Yes	Non-Smoking	Yes
Pet-Free	Yes				

Construction Features

Hull Material Fiberglass

Features










Stock # 402182









Stock # 402182

Safety Equipment

Horn
Halon Fire Suppression
Grab Rails





Pop Sells 5717 Bessie Drive Sarasota, Florida 34233



Contact Robert Hill (410) 371-5657 roberth@popsells.com

1983 Universal Trawler Litton Europa 41

Stock # 402182



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on May 22, 2025 1:24 AM Please view this listing online for up-to-date information: https://www.popsells.com/view/402182