



Stock # 403033



\$12,500.00

\$18,500.00

Year 1995
Type Powerboat
Brand Seaswirl
Category Walkarounds
Model 2150 Striper
Length (LOA) 21' 4"

Hours 562

Location The Colony, Texas

Closest Major City Frisco, TX

Storage Status Not currently in storage

1995 Seaswirl 2150 Striper for sale in Texas! 150 HP motor!

Introducing the 1995 Seaswirl 2150 Striper! She's located in The Colony, Texas and is ready for a new home! This walkaround boat has a length of 21' 4" and is powered by an Evinrude Ocean Pro 150 HP two-stroke engine with 562 hours of use. This boat has had some updates as you can see in the photos and video. Notice the newer seats. She's got a cabin to relax in and get out of the sun on those extremely hot days. The bimini is recently installed and in great shape. Don't miss out on this one. She's priced to sell. Call today to schedule a viewing or to make an offer.

Read the entire description on the website by scanning the QR code below.







Stock # 403033

Details and Specifications

# of Engines	1	Engine Brand	Evinrude	Engine Model	150 Ocean Pro
Engine Hours	562	Engine Size	150 hp	Fuel Type	Gasoline
Configuration	Outboard - 2 Stroke				

Dimensions & Specifications

Length (LOA) 21' 4"

Trailer Details

Included No

Accommodations & Passengers

of Cabins 1 # of Berths 1 Has Generator No

Has Air No
Conditioning Yes Pet-Free Yes







Stock # 403033

$C \cap$	netru	iction	Features

 Hull Material
 Fiberglass
 Exterior Color
 White
 Interior Color
 Interior Wood

Finish

Features

Accommodations

• Cuddy Cabin • V Berth

Deck Gear


- Bow Rail Rod Holders Anchor Bimini
- Captain's Chair
 Passenger Seat
 Steering Wheel
 Swim Ladder (Stern)

Electrical Systems

• Fuel Gauge • Hour Meter







Stock # 403033

Mechanical Systems

• Throttle/shift: Mech

Oil Injection Tank

• Power Trim & Tilt


Navigational Equipment

VHF


· Fish Finder: Humminbird







Stock # 403033



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.

