

**Pop Sells** 5717 Bessie Drive Sarasota, Florida 34233

2017 Sunstar 32YE

Stock # 420904



\$66,700

Year	2017		
Туре	Motor		
Brand	Sunstar		
Manufactured By	Winnebago		
Category	Class A		
Model	32YE		
Length	33' 0"		
Miles	47,000		
Location	Leland, North Carolina		
Closest Major City	Wilmington, NC		

#### 2017 SUNSTAR BY WINNEBAGO 33YE CLASS A FOR GAS SLEEPS UP TO 5

Located in Leland, North Carolina, this used Sunstar 32YE, manufactured by Winnebago, is a great Class A RV for sale. Drive this Sunstar RV on a journey to your favorite destination, or discover a new favorite. The 32YE model has lots of space for your family and friends, and all your camping gear and outdoor toys. Drive this Sunstar RV across the country with the power of a Ford engine. Don't miss out on your opportunity to own this good condition Sunstar RV!

Read the entire description on the website by scanning the QR code below.



Information generated on Aug 21, 2024 7:30 AM Please view this listing online for up-to-date information: https://www.popsells.com/view/420904 Рор



# 2017 Sunstar 32YE

Stock # 420904

### **Details and Specifications**

Engine Brand	Ford	Miles	47,000	Fuel Type	Gasoline
Dimensions	& Specific	ations			
Length	33'				
Accommoda	ations & Pa	issengers			
Accommoda Sleep Capacity		ISSENGERS Bunk Beds	No	# of Slides	2
			No	# of Slides	2
			No	# of Slides	2
	7 5	Bunk Beds	No	# of Slides	2





**Pop Sells** 5717 Bessie Drive Sarasota, Florida 34233

Pop

## 2017 Sunstar 32YE

1

Stock # 420904

### Living Areas

# of Full Bathrooms # of Half Bathrooms 3



Information generated on Aug 21, 2024 7:30 AM Please view this listing online for up-to-date information: https://www.popsells.com/view/420904



**Pop Sells** 5717 Bessie Drive Sarasota, Florida 34233

Pop

## 2017 Sunstar 32YE

Stock # 420904



#### Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.

