



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact Erica Fischer
(614) 738-6211
ericaf@popsells.com

2014 Malibu 23 LSV

Stock # 423629



\$65,596

Year	2014
Type	Power
Brand	Malibu
Category	Ski/Wakeboard Boats
Model	23 LSV
Length (LOA)	23' 0"
Hours	Unavailable
Location	Golden, Colorado
Closest Major City	Lakewood, CO
Storage Status	Not currently in storage

Located in Golden, Colorado, this 23-foot used Malibu 23 LSV is a great wake/ski boat. Malibu are durable and reliable fiberglass runabout boats. This Malibu boat comes with a trailer, included in the price of the boat sale. The 23 LSV has lots of space for your family and friends, and all your boating gear. Don't miss out on your opportunity to own this good condition Malibu marine!

Read the entire description on the website by scanning the QR code below.



Information generated on Oct 6, 2024 7:01 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/423629>



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact Erica Fischer
(614) 738-6211
ericaf@popsells.com

2014 Malibu 23 LSV

Stock # 423629

Details and Specifications

Engine & Mechanical

Engine Hours	Unavailable	Fuel Capacity	65 gals
---------------------	-------------	----------------------	---------

Dimensions & Specifications

Length (LOA)	23'	Beam	8' 6"	Minimum Draft	2' 8"
---------------------	-----	-------------	-------	----------------------	-------

Trailer Details

Included	Yes	Breakaway Hitch	No
-----------------	-----	------------------------	----

Construction Features

Hull Material	Fiberglass
----------------------	------------



Information generated on Oct 6, 2024 7:01 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/423629>

Pop

Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233

Pop

Contact Erica Fischer
(614) 738-6211
ericaf@popsells.com

2014 Malibu 23 LSV

Stock # 423629



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Oct 6, 2024 7:01 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/423629>