



## Pop Sells

5717 Bessie Drive  
Sarasota, Florida 34233



**Contact Steve Towns**  
(269) 326-0762  
stevet@popsells.com

# 2016 Gekko Revo 7.1

Stock # 426343



## \$46,900

~~\$48,900~~

<b>Year</b>	2016
<b>Type</b>	Powerboat
<b>Brand</b>	Gekko
<b>Category</b>	Ski/Wakeboard Boats
<b>Model</b>	Revo 7.1
<b>Length (LOA)</b>	23' 3"
<b>Hours</b>	Unavailable
<b>Location</b>	Cedar Lake, Indiana
<b>Closest Major City</b>	Bloom, IL
<b>Storage Status</b>	Not currently in storage

### Awesome Ski/wakeboard boat! Lots of room for your passengers and gear!

Located in Cedar Lake, Indiana, this 23-foot used Gekko Revo 7.1 is a great wake/ski boat. Powered by a 330hp Indmar engine, this Gekko boat can get you to your favorite spot or help you discover a new one. The Revo 7.1 has lots of space for your family and friends, and all your boating gear. Don't miss out on your opportunity to own this good condition Gekko marine!

Read the entire description on the website by scanning the QR code below.



Information generated on May 14, 2025 11:40 PM  
Please view this listing online for up-to-date information:  
<https://www.popsells.com/view/426343>



**Pop Sells**  
5717 Bessie Drive  
Sarasota, Florida 34233



**Contact Steve Towns**  
(269) 326-0762  
stevet@popsells.com

# 2016 Gekko Revo 7.1

Stock # 426343

## Details and Specifications

### Engine & Mechanical

# of Engines	1	Engine Brand	Indmar	Engine Hours	Unavailable
Engine Size	330 hp	Fuel Type	Gasoline		

### Dimensions & Specifications

Length (LOA)	23' 3"
--------------	--------

### Trailer Details

Included	No
----------	----

### Accommodations & Passengers

Non-Smoking	Yes	Pet-Free	Yes
-------------	-----	----------	-----



Information generated on May 14, 2025 11:40 PM  
Please view this listing online for up-to-date information:  
<https://www.popsells.com/view/426343>

Pop

## Pop Sells

5717 Bessie Drive  
Sarasota, Florida 34233



Contact Steve Towns  
(269) 326-0762  
stevet@popsells.com

# 2016 Gekko Revo 7.1

Stock # 426343



**Scan the QR code or click the link in the footer to view more photos.**

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on May 14, 2025 11:40 PM  
Please view this listing online for up-to-date information:  
<https://www.popsells.com/view/426343>