



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Jorge Rodriguez
(305) 588-2969
jorger@popsells.com

2022 Bentley Cruise 240

Stock # 434741



\$27,800

Year	2022
Type	Powerboat
Brand	Bentley
Category	Pontoon Boats
Model	Cruise 240
Length (LOA)	24' 0"
Hours	Unavailable
Location	Aventura, Florida
Closest Major City	Miramar, FL

Cruise 240 pontoon powered by a 90HP Suzuki motor, Captivating comfort and luxury you can afford!

Located in Aventura, Florida, this 24-foot used Bentley Cruise 240 is a great pontoon boat. Get ready for a relaxing day on the water with your family and friends! Powered by a 90hp Suzuki engine, this Bentley boat can get you to your favorite spot or help you discover a new one. The Cruise 240 has lots of space for your family and friends, and all your boating gear. Don't miss out on your opportunity to own this good condition Bentley pontoon!

Read the entire description on the website by scanning the QR code below.



Information generated on Jan 15, 2025 6:17 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/434741>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Jorge Rodriguez
(305) 588-2969
jorger@popsells.com

2022 Bentley Cruise 240

Stock # 434741

Details and Specifications

Engine & Mechanical

# of Engines	1	Engine Brand	Suzuki	Engine Hours	Unavailable
Engine Size	90 hp	Fuel Type	Gasoline	Configuration	Outboard - 4 Stroke

Dimensions & Specifications

Length (LOA)	24'
---------------------	-----

Trailer Details

Included	No
-----------------	----

Accommodations & Passengers

Non-Smoking	Yes	Pet-Free	Yes
--------------------	-----	-----------------	-----



Information generated on Jan 15, 2025 6:17 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/434741>





Pop Sells
 5717 Bessie Drive
 Sarasota, Florida 34233



Contact Jorge Rodriguez
 (305) 588-2969
 jorger@popsells.com

2022 Bentley Cruise 240

Stock # 434741



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Jan 15, 2025 6:17 AM
 Please view this listing online for up-to-date information:
<https://www.popsells.com/view/434741>