



Stock # 436018



\$23,000.00

\$25,000.00

Year 2017 Type Powerboat **Brand** Tahoe Category Deck Boats Model 215 XI Length (LOA) 21' 5" Hours Unavailable Fresno, California Location Storage Status Not currently in storage

2017 Tracker Tahoe Marine series 215 XI deck boat powered by Mercruiser engine

Get ready for endless days on the water onboard this 2017 Tahoe 215 XI. Whether you're cruising with family or hitting the water for an adrenaline-pumping adventure, this 21-foot beauty delivers.

21' + of room for all your friends and family to relax and enjoy the ride. Powered by an efficient Mercruiser to give you smooth rides and thrilling speeds.

Plush seating throughout, including sunpad and convertible bow for ultimate relaxation.

Plenty of storage space for all your gear, from skis to fishing rods.

Take your weekends to the next level with this stunning 2017 Tahoe 215 Xi! It's ready for yo...

Read the entire description on the website by scanning the QR code below.







Stock # 436018

Details and Specifications

of Engines	1	Engine Year	2017	Engine Brand	Mercruiser
ingine Hours	Unavailable	Fuel Type	Gasoline	Fuel Capacity	36 gals
Propeller Material	Stainless Steel	Drive Brand	Mercruiser	Drive Model	Alpha One
Orive Type	Stern Drive	Configuration	Inboard/Outboard		

Dimensions	& Specific	ations			
Length (LOA)	21' 5"	Beam	8' 6"	Dry Weight	3,510 lbs

ncluded No

Has Generator No Has Air No Conditioning	Accommodations & Pa	assengers		
	Has Generator No	Has Air Conditioning	No	







Stock # 436018

Construction Features

Hull Material Fiberglass Hull Shape Modified Vee Exterior Color White, Red

Features

Deck Gear

- Beverage Holders
- Bimini
- Bow Seating
- · Captain's Chair

- Cockpit Seating
- Swim Ladder (Stern)
- Swim Platform
- Windshield Walk

Through

Electrical Systems

Stereo

Mechanical Systems

- Bilge Pump
- Power Trim & Tilt
- · Throttle/shift: Mech





Stock # 436018

Navigational Equipment

• Navigation Lights

• GPS / Plotter:

Humminbird







Stock # 436018



















Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.

