



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Paul Herman
(843) 209-3818
paul@popsells.com

1984 Monk 36 Trawler

Stock # 448619



\$35,000.00

~~\$39,900.00~~

Year	1984
Type	Powerboat
Brand	Monk
Category	Trawlers
Model	36 Trawler
Length (LOA)	36' 0"
Hours	5,400
Location	Georgetown, South Carolina
Closest Major City	Mount Pleasant, SC
Storage Status	Not currently in storage

Well Equipped 1984 Monk 36 Twin Engine Trawler With Numerous Recent Updates!

1984 Monk 36 Trawler for sale.

This model brings several uses and provides very nice interior and exterior space under 40ft vessel.

This vessel is an experienced cruiser, cosmetically needs work and elbow grease. The largest mechanical issue, the generator does not operate and the seller feels it would need to be replaced.

Has newer electronics that are paired and have radar on both flybridge and interior helm.

Two Racor 500 filters, 4 on engine twist on fuel filters, Oak mast rebuilt with all LED lights, clipper wind instrument, omni-directional TV antenna, New battery box and cabling. Four ...

Read the entire description on the website by scanning the QR code below.



Information generated on Jun 1, 2025 1:54 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/448619>



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact Paul Herman
(843) 209-3818
paul@popsells.com

1984 Monk 36 Trawler

Stock # 448619

Details and Specifications

Engine & Mechanical

# of Engines	2	Engine Year	1984	Engine Brand	Perkins
Engine Model	6-354	Engine Hours	5,400	Engine Size	135 hp
Fuel Type	Diesel	Propeller Material	Bronze	Configuration	Inboard

Dimensions & Specifications

Length (LOA)	36'	Beam	14'	Minimum Draft	2' 4"
--------------	-----	------	-----	---------------	-------

Trailer Details

Included	No
----------	----



Information generated on Jun 1, 2025 1:54 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/448619>



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact Paul Herman
(843) 209-3818
paul@popsells.com

1984 Monk 36 Trawler

Stock # 448619

Accommodations & Passengers

# of Cabins	2	Sleeping Capacity	5	# of Berths	3
Can Live Aboard	Yes	Has Generator	Yes not operational	Has Air Conditioning	Yes 12000 BTU
Non-Smoking	Yes	Pet-Free	Yes		

Construction Features

Designer	Monk	Hull Material	Fiberglass	Hull Shape	Deep Vee
Exterior Color	White	Interior Color	Multiple		

Features

Accommodations

- Cabin Lighting
- Cabinets
- Head
- Microwave
- Shower
- Sink - Galley
- Stateroom - Aft
- Stove
- Window Treatments



Information generated on Jun 1, 2025 1:54 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/448619>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Paul Herman
(843) 209-3818
paul@popsells.com

1984 Monk 36 Trawler

Stock # 448619

Construction Features

- Bottom Paint Antifouling

Deck Gear

- Anchor
- Anchor Rode
- Bimini
- Bow Pulpit
- Bow Rail
- Cleats - Fixed
- Dinghy Lift
- Swim Platform
- Transom - Closed

Electrical Systems

- 110v AC Outlets
- 12 V DC Outlets
- Battery Switch
- Courtesy Lights
- Fuel Gauge
- Hour Meter
- Tachometer

Mechanical Systems

- Holding Tank
- Throttle/shift: Mech
- Water Tank
- Bilge Pump
- Rudder: 2



Information generated on Jun 1, 2025 1:54 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/448619>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Paul Herman
(843) 209-3818
paul@popsells.com

1984 Monk 36 Trawler

Stock # 448619

Navigational Equipment

- Navigation Lights
- VHF
- Compass
- GPS/ Fishfinder/ Plotter:
Garmin
- Radar Dome: Garmin

Safety Equipment

- Yacht Certified



Information generated on Jun 1, 2025 1:54 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/448619>



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Paul Herman
(843) 209-3818
paul@popsells.com

1984 Monk 36 Trawler

Stock # 448619



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Jun 1, 2025 1:54 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/448619>