



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Bill Poleatewich
(603) 608-7561
bill@popsells.com

2017 Supreme S211

Stock # 454997



\$49,900.00

Year	2017
Type	Powerboat
Brand	Supreme
Category	Ski/Wakeboard Boats
Model	S211
Length (LOA)	23' 0"
Hours	Unavailable
Location	East Wareham, Massachusetts
Closest Major City	Plymouth, MA
Storage Status	Not currently in storage

Well Maintained 2017 Supreme S211 Wakeboard Boat With Low Hours!

Located in East Wareham, Massachusetts, this 23-foot used Supreme S211 is a great wake/ski boat. Powered by a Crusader engine, this Supreme boat can get you to your favorite spot or help you discover a new one. This Supreme boat comes with a Homemade trailer, included in the price of the boat sale. The S211 has lots of space for your family and friends, and all your boating gear. Don't miss out on your opportunity to own this good condition Supreme marine!

Read the entire description on the website by scanning the QR code below.



Information generated on Jun 18, 2025 11:47 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/454997>



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact Bill Poleatewich
(603) 608-7561
bill@popsells.com

2017 Supreme S211

Stock # 454997

Details and Specifications

Engine & Mechanical

# of Engines	1	Engine Brand	Crusader	Engine Hours	Unavailable
Fuel Type	Gasoline	Configuration	Inboard		

Dimensions & Specifications

Length (LOA)	23'
--------------	-----

Trailer Details

Included	Yes	Trailer Brand	Homemade	Breakaway Hitch	No
----------	-----	---------------	----------	-----------------	----



Information generated on Jun 18, 2025 11:47 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/454997>

Pop

Pop Sells



5717 Bessie Drive
Sarasota, Florida 34233



Contact Bill Poleatewich
(603) 608-7561
bill@popsells.com

2017 Supreme S211

Stock # 454997



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Jun 18, 2025 11:47 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/454997>