



Stock # 459650



\$68,000.00

Year1998TypeSailboatBrandGeminiCategoryCatamaranModelM105Length (LOA)35' 0"

**Hours** Unavailable

**Location** Cudjoe Key, Florida

Closest Major City Key West, FL
Storage Status In the water

# M105 Cat Powered w/ 30hp Westerbeke Diesel. Fresh Bottom Job and Main Sail, 9.9 Yamaha Long Shaft Kicker, Marine AC, More!!

Looking for a proven, stable, fun, and fast, ready-to-sail CAT that can fit into a standard slip? This CAT with retractable daggerboards, 1.6 ft draft, is the one to take you and your guests to those places you've dreamed of sailing in pristine waters of less than 2 ft effortlessly. "Easy Going" resides in the beautiful Florida Keys with a short sail out to beautiful ocean waters.

Powered by a trustworthy 30hp Westerbeke diesel and a 9.9 longshaft 9.9 Yamaha kicker, this Gemini has a spacious layout, all the amenities wanted on a cruising catamaran, including Garmin electronics, fresh bottom job and mainsail, Queen size bed in the ma...

Read the entire description on the website by scanning the QR code below.







Stock # 459650

### **Details and Specifications**

# of Engines	1	Engine Brand	Westerbeke Diesel	Engine Hours	Unavailable
Engine Size	30 hp	Fuel Type	Diesel	Fuel Capacity	36 gals
Configuration	Inboard/Outboard				

Length (LOA)	35'	Beam	14'	Minimum Draft 1'6"
Cockpit Location	Aft			

Trailer De	tails	
Included	No	







Stock # 459650

Accommodations & Passengers					
Can Live Aboa	<b>rd</b> Yes	Water Capacity 60 gals	Waste Capacity 1	.8 gals	
Has Air Conditioning	Yes Marine Air / 2 additional units	Non-Smoking Yes	Pet-Free Y	e'es	

	<b>Features</b>

Designer	Tony Smith	Hull Material	Fiberglass	Hull Shape	CAT
----------	------------	---------------	------------	------------	-----

#### **Features**

#### **Accommodations**

• Queen Mattress

/bedding: New

#### **Electrical Systems**

· Solar Panel







Stock # 459650

#### **Navigational Equipment**

• GPS / Plotter: Garmin







Stock # 459650



















Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.

