



Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Andy Baker
(941) 914-5012
andy@popsells.com

2018 Sandpiper 383RBLOK

Stock # 459892



\$48,500.00

Year	2018
Type	Trailer
Brand	Sandpiper
Manufactured By	Forest River
Category	Fifth Wheel
Model	383RBLOK
Length	42' 0"
Miles	Unavailable
Location	Pinellas Park, Florida
Closest Major City	St. Petersburg, FL
Storage Status	Not currently in storage

Excellent 2018 Forest River Sandpiper 383RBLOK Fifth Wheel RV!

Located in Pinellas Park, Florida, this used Sandpiper 383RBLOK, manufactured by Forest River, is a great fifth wheel trailer for sale. Sandpiper by Forest River produces a series of travel trailers and fifth wheel trailers for the recreational vehicle marketplace. Tow this Sandpiper RV on a journey to your favorite destination, or discover a new favorite. The 383RBLOK model has lots of space for your family and friends, and all your camping gear and outdoor toys. Breathe easy knowing that this 383RBLOK has never had a cigarette or pets aboard. Don't miss out on your opportunity to own this good condition Sandpiper RV!

Read the entire description on the website by scanning the QR code below.



Information generated on Aug 20, 2025 4:02 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/459892>



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233



Contact Andy Baker
(941) 914-5012
andy@popsells.com

2018 Sandpiper 383RBLOK

Stock # 459892

Details and Specifications

Dimensions & Specifications

Length 42'

Accommodations & Passengers

Sleep Capacity 11 **Bunk Beds** Yes **# of Slides** 4

Living Areas

Non-Smoking Yes **Pet-Free** Yes



Information generated on Aug 20, 2025 4:02 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/459892>



Pop Sells


5717 Bessie Drive
Sarasota, Florida 34233



Contact Andy Baker
(941) 914-5012
andy@popsells.com

2018 Sandpiper 383RBLOK

Stock # 459892



Scan the QR code or click the link in the footer to view more photos.

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Aug 20, 2025 4:02 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/459892>