

**Pop**

**Pop Sells**

5717 Bessie Drive  
Sarasota, Florida 34233



**Contact Rhonda Rydstrom**  
(949) 922-7483  
rhondar@popsells.com

# 2017 Carado AXION

Stock # 460646



**\$50,000.00**

<b>Year</b>	2017
<b>Type</b>	Motorhome
<b>Brand</b>	Carado
<b>Category</b>	Class B
<b>Model</b>	AXION
<b>Length</b>	18' 0"
<b>Miles</b>	43,000
<b>Location</b>	San Clemente, California
<b>Closest Major City</b>	Oceanside, CA

## 2017 Carado Axion Class B powered by RAM with low miles!

Located in San Clemente, California, this used Carado AXION is a great Class B RV for sale. Drive this Carado RV on a journey to your favorite destination, or discover a new favorite. Breathe easy knowing that this AXION has never had a cigarette or pets aboard. Drive this Carado RV across the country with the power of a Ram engine. Don't miss out on your opportunity to own this good condition Carado RV!

Read the entire description on the website by scanning the QR code below.



Information generated on Aug 6, 2025 10:44 AM  
Please view this listing online for up-to-date information:  
<https://www.popsells.com/view/460646>



**Pop Sells**  
5717 Bessie Drive  
Sarasota, Florida 34233



**Contact Rhonda Rydstrom**  
(949) 922-7483  
rhondar@popsells.com

# 2017 Carado AXION

Stock # 460646

## Details and Specifications

### Engine & Mechanical

Engine Brand	Ram	Miles	43,000	Fuel Type	Gasoline
--------------	-----	-------	--------	-----------	----------

### Dimensions & Specifications

Length	18'
--------	-----

### Accommodations & Passengers

Sleep Capacity	2	Bunk Beds	No	# of Slides	0
----------------	---	-----------	----	-------------	---

### Living Areas

Non-Smoking	Yes	Pet-Free	Yes
-------------	-----	----------	-----



Information generated on Aug 6, 2025 10:44 AM  
Please view this listing online for up-to-date information:  
<https://www.popsells.com/view/460646>



## Pop Sells

5717 Bessie Drive  
Sarasota, Florida 34233



**Contact Rhonda Rydstrom**  
(949) 922-7483  
rhondar@popsells.com

# 2017 Carado AXION

Stock # 460646



**Scan the QR code or click the link in the footer to view more photos.**

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Aug 6, 2025 10:44 AM  
Please view this listing online for up-to-date information:  
<https://www.popsells.com/view/460646>