



Contact Pop (941) 257-0111

1982 Sanger 20 MINI DAY CRUISER V DRIVE

Stock # 73535

\$8,500

\$17,500

Year 1982 Type Power Brand Sanger

Category High Performance

20 MINI DAY CRUISER V

DRIVE

Length (LOA) 19' 0" **Hours** 320

Location Post Falls, Idaho

Closest Major

City Coeur d'Alene, ID

Storage Status Not currently in storage

GREAT CLASSIC SANGER AND ALL FRESHWATER!

Nice 1982 Sanger Mini Day Cruiser V Drive! - Built in Fresno CA and current owner is only the 2nd owner. - 2006 502 ci. Big Block Chevy with 400 turbo 3 speed Transmission with Cassel Vdrive. - Lots of really nice parts on the boat - Chrome oil and trans coolers. - Glenwood polished Exhaust Manifolds. - Mickey Thompson valve covers. - 14 qt. oil pan. - MSD Ignition. - Holley intake manifold. - Elderbrock Carburetor. - Chrome Aluminum Cavitation plates. - Hand and foot cavitation pedal.

Read the entire description on the website by scanning the QR code below.







Contact Pop (941) 257-0111

1982 Sanger 20 MINI DAY CRUISER V DRIVE

Stock # 73535

Details and Specifications

# of Engines	1	Engine Year	1982	Engine Brand	Custom
Engine Model	502 Big Block	Engine Hours	320	Engine Size	550 hp
Fuel Type	Gasoline	Fuel Capacity	30 gals	Propeller Material	Stainless
Max Speed	85 mph	Cruising Speed	40 mph	Drive Brand	Cassel
Drive Model	3 Speed Turbo 400	Drive Type	V-Drive	Configuration	Inboard

Included	Yes	Trailer Year	1982	Trailer Brand	Carrier
Trailer Model	UV	Trailer Material	Steel	# Axles	2
# Brakes	2	Breakaway Hitch	No		







Contact Pop (941) 257-0111

1982 Sanger 20 MINI DAY CRUISER V DRIVE

Stock # 73535

Passenger Capacity	8	Has Generator No	Has Air No Conditioning

Construction Features

DesignerSangerHull MaterialFiberglassHull ShapeModified Vee

Features

Electrical Systems

- Battery Perko Switch
- Circuit Breaker Panel
- Docking Lights
- Fuel Gauge

Horn

- Hour Meter
- Speedometer
- · Accessory Switches

- Alternator
- Battery: (2)

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.

