

**Pop Sells** 5717 Bessie Drive Sarasota, Florida 34233



### 2013 Monterey 244 FSX

Stock # 76058

### \$54,500

Year	2013
Туре	Power
Brand	Monterey
Category	Bowriders
Model	244 FSX
Length (LOA)	24' 0"
Hours	40
Location	Volo, Illinois
Closest Major City	Avon, IL
Storage Status	Not currently in storage

#### 2014 SURVEY DONE - 40 HOURS!

2013 MONTEREY 244FSX, Over \$80k New, comes with Dual Axle TRAILER, Only 40 HOURS & LIKE BRAND NEW !!!

Just some of the things on the boat include:

Stereo Upgrade Package: 2 tweeters, 4 wet sound speakers, Wet sound sub woofer, Dash and stern remotes

Stereo details: fusion satellite ready AM/FM with built in iPod dock and 4 speakers, Electrical Battery tray, weatherproof electrical system with individual circuit protection

Storage: in-floor ski with gas assisted hatch cover, fiberglass liner & dry deck Storage, port dash with full size lockable door, molded fiberglass liner with drain, side pane...

Read the entire description on the website by scanning the QR code below.







# 2013 Monterey 244 FSX

Stock # 76058

### **Details and Specifications**

# of Engines	1	Engine Year	2013	Engine Brand	Mercruiser
Engine Model	350 Magnum MPI	Engine Hours	40	Engine Size	300 hp
Fuel Type	Gasoline	Fuel Capacity	62 gals	Drive Brand	Mercruiser
Drive Model	Bravo III	Configuration	Inboard/Outboard		
Dimensions	& Specificatio				
	& Specificatio	ns Beam	8' 6"	Dry Weight	4,300 lbs
Dimensions	24'		8' 6"	Dry Weight	4,300 lbs







### 2013 Monterey 244 FSX

Stock # 76058

Water Capacit	<b>y</b> 10 gals	Has Generato	r No	Has Air Conditioning	No
Constructio	on Features				
Hull Material	Fiberglass	Hull Shape	V	Exterior Color	White/black
Interior Color	White				






**Pop Sells** 5717 Bessie Drive Sarasota, Florida 34233



# 2013 Monterey 244 FSX

Stock # 76058

#### **Features**



- Hand Rails
  Fuel Injected
  Bilge Pump
  Cockpit Type: Open
- Engine Cylinders: 8








# 2013 Monterey 244 FSX

Stock # 76058



This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.

