



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233

Pop
Contact Pop
(941) 257-0111

1988 Sea Ray 305 Sedan Bridge

Stock # 761

\$19,000

~~\$21,900~~

Year	1988
Type	Power
Brand	Sea Ray
Category	Motoryachts
Model	305 Sedan Bridge
Length (LOA)	30' 0"
Hours	700
Location	Lee County, Florida
Storage Status	Not currently in storage

1988 Sea Ray Sedan Bridge 30 ft. Twin 260 Mercruisers (straight inboards.) VGC. Has A/C, generator, shore power, VHF, stereo, 2 private state rooms, stand up head & shower, fridge, microwave, 2 burners, double sink, ice maker. Approx. 700 hours. Stock ID: AAM-3706085

Specs

- Length Overall (LOA): 30'

Take a look at ALL ***46 PICTURES*** OF THIS VESSEL ON OUR MAIN SITE AT POPYACHTS DOT COM. At brokerage International we will always provide you with a TRUE REPRESENTATION of every vessel we market. We are a full-service brokerage company, ready to assist you with all the details, including photographing, ins...

Read the entire description on the website by scanning the QR code below.



Information generated on Jul 19, 2024 6:43 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/761>



1988 Sea Ray 305 Sedan Bridge

Stock # 761

Details and Specifications

Engine & Mechanical

# of Engines	2	Engine Year	1988	Engine Brand	MerCruiser
Engine Model	Vgc	Engine Hours	700	Engine Type	Inboard
Engine Size	260 hp	Fuel Type	Gasoline	Cruising Speed	23 mph
Configuration	Inboard				

Dimensions & Specifications

Length (LOA)	30'	Beam	11' 6"	Minimum Draft	2' 6"
--------------	-----	------	--------	---------------	-------

Trailer Details

Included	No
----------	----

Accommodations & Passengers

Has Generator	No	Has Air Conditioning	No
---------------	----	----------------------	----





Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233

Pop
Contact Pop
(941) 257-0111

1988 Sea Ray 305 Sedan Bridge

Stock # 761

Construction Features

Hull Material	Fiberglass	Exterior Color	White
----------------------	------------	-----------------------	-------

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Jul 19, 2024 6:43 AM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/761>