



Pop Sells
5717 Bessie Drive
Sarasota, Florida 34233

Pop
Contact Pop
(941) 257-0111

2004 Sea Fox 217 CC

Stock # 90178

\$15,000

Year	2004
Type	Power
Brand	Sea Fox
Category	Center Consoles
Model	217 CC
Length (LOA)	21' 3"
Hours	Unavailable
Location	Marco Island, Florida
Closest Major City	Naples, FL
Storage Status	Not currently in storage

Ready to go!

2004 Sea Fox 217 CC that is ready to go fishing!

This beauty has been kept out of the water on a lift and the hull shows smooth and shiny. The Captain's chair/leaning post has a custom cover as well as the console. Under gunwale rod storage with two on each side. Console has cubby with porta potty. Large casting platform forward with generous storage underneath. A bow pulpit neatly holds the anchor ready for deployment with line storage below. Aft you will find a large aerated live well starboard and an equally large fish box port. The leaning post back support is removable and is equipped with 4 rod holders on the back...

Read the entire description on the website by scanning the QR code below.



Information generated on Oct 23, 2024 7:02 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/90178>



2004 Sea Fox 217 CC

Stock # 90178

Details and Specifications

Engine & Mechanical

# of Engines	1	Engine Year	2005	Engine Brand	Mercruiser
Engine Model	150 Optimax	Engine Hours	Unavailable	Engine Size	150 hp
Fuel Type	Gasoline	Configuration	Outboard - 2 Stroke		

Dimensions & Specifications

Length (LOA)	21' 3"	Beam	8' 5"	Minimum Draft	1' 3"
Dry Weight	2,300 lbs				

Trailer Details

Included	No
----------	----

Accommodations & Passengers

Passenger Capacity	8	Has Generator	No	Has Air Conditioning	No
--------------------	---	---------------	----	----------------------	----





Pop Sells

5717 Bessie Drive
Sarasota, Florida 34233



Contact Pop
(941) 257-0111

2004 Sea Fox 217 CC

Stock # 90178

Construction Features

Hull Material Fiberglass

This information was provided to Pop Sells, LLC by the Seller and is believed to be accurate at the time of publication. We recommend an inspection by a qualified professional to ascertain the overall condition and function of structure and mechanical components.



Information generated on Oct 23, 2024 7:02 PM
Please view this listing online for up-to-date information:
<https://www.popsells.com/view/90178>